

BARRETT BARN DESIGNATION REPORT

CHANGES MADE

Page 7

Original: ...Casson painting is the principal reason the barn should be designated. Since only the front of the barn that is visible in the painting, it is that feature which should be designated.

Modified: ...Casson painting is the principal reason the barn should be designated. Since only the front of the barn is visible in the painting, that facade should be emphasized in the designation.

Page 9

Original:

Description of Heritage Attributes

- Location on the side of a hill on the south-western side of Confederation Street in the village of Glen Williams
- Two storey form with cross gable pitched roof on front (east-west) section
- Front gabled wing with wide barn/garage door opening with four/three fixed pane window above
- Side door opening and two side windows within the front wing
- Barn board on front wing
- Original wooden door on back (north-south) wing
- Window opening facing the road on back wing
- Two sets of original windows facing south on back wing

Description of Heritage Attributes

- The setback, placement and orientation of the Barrett Barn is at the end of a driveway on the south-western side of Confederation Street in the village of Glen Williams. A hill rises on the north side and continues downward on the south side. The garage door opening faces Confederation Street. The second story of the building is level with the lawn on the top of the hill.
- The scale, form and massing of the two-storey form barn with cross gable pitched roof, one running east-west on the front section, and a second running north-south on the rear section of an L-shaped building

EASTERLY (FRONT) SECTION:

- Front gabled wing with wide barn/garage door opening at the first storey, with four/three fixed pane window on the second storey, all facing Confederation Street
- South side door opening with one ground floor window and a second-floor window in line with the first-floor door opening
- Barn board cladding on the principal (east) and south side elevations

WESTERLY (REAR) SECTION:

- Original wooden door opening facing Confederation Street (currently covered in metal siding)
- Original window opening facing Confederation Street (currently covered in metal siding)

- On the south elevation, paired rectangular window openings with fixed pane wood windows with 3/2 divided panes

NOTE: The c.1875 residential building within the property at 68 Confederation Street has been significantly altered and is not identified as a heritage attribute.